

MOTUL

こんな方には

ATF交換がおすすめ

- ✓ 変速時のショックが気になり始めた
- ✓ 加速時にもたつく
- ✓ 燃費の悪化が気になる
- ✓ 長く万全の状態であらに乗りた

3つのメリット

- ✓ 2年または2万kmに一度の定期交換をお勧めしています

1.



シフトショックの低減により、スムーズな加速が復活!

2.



ギヤの動きがスムーズになり、パワー伝達効率が向上し燃費が改善!

3.



汚れを排出する事で機械の耐久性向上!

※裏面にATF適合表が御座います。

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
フォルクスワーゲン アウディ	G 052 533, G 053 001, G 053 001 A2, G 055 005, G 055 162, G 055 540, G 060 162, G 060 540 A2				
	G 052 533, G 055 005				
	Tip-tronic, G 052 025, G 052 162, G 052 533, G 052 990, G 055 005, G 055 025, TL 52 162				
	DSG, S-tronic, G 009 317, G 052 171, G 052 178, G 052 182, G 052 512, G 052 527, G 052 529, G 052 726, G 052 798, G 055 512, G 055 529, G 060 726, G 070 726, TL 52 182				
	Multi-tronic, G 052 180, G 052 516, TL 52 116, TL 52 180, TL 52 516				
メルセデスベンツ	A 001 989 45 03, A 001 989 68 03, A 001 989 77 03, A 001 989 78 03, A 002 989 06 03, MB 236.12, MB 236.14, MB 236.15 (Except FE benefits), MB 236.16 (Except FE benefits), MB 236.17 (Except FE benefits), MB 236.41				
	MB 236.12				
	A 001 989 22 03, MB 236.1, MB 236.10, MB 236.11, MB 236.12, MB 236.3, MB 236.5, MB 236.7, MB 236.9				
	A 001 989 86 03, MB 236.24, MB 236.25				
	A 001 989 46 03, MB 236.20				
BMW	83 22 0 142 516, 83 22 0 397 114, 83 22 0 403 248, 83 22 0 403 249, 83 22 0 432 807, 83 22 2 152 426, 83 22 2 163 514, 83 22 2 289 720, 83 22 2 305 396 (ATF2), 83 22 2 305 397, 83 22 2 355 599, 83 22 2 355 601, 83 22 2 413 477 (ATF7), 83 22 9 400 275, 83 22 9 407 738, 83 22 9 407 858, 83 22 9 407 859, ATF 3+, ATF6, L12108				
	83 22 0 142 516, 83 22 2 305 396 (ATF2)				
	81 22 9 400 272, 83 22 0 026 922, 83 22 0 142 516, 83 22 0 402 413, 83 22 2 305 396 (ATF2), 83 22 9 407 765, 83 22 9 407 807, ATF2, ETL 7045E, ETL 8072B, LA2634, LT 71141				
	83 22 0 306 816, 83 22 0 397 244, 83 22 0 440 214, 83 22 2 147 477, 83 22 2 148 578, 83 22 2 148 579, 83 22 2 167 666, 83 22 2 409 710, DCTF-1, DKG, DTF 1, MTF LT-3, MTF-LT-5				
	83 22 0 136 376, 83 22 0 429 154, EZL 799, EZL 799 A				
MINI	83 22 2 413 477 (ATF7)				
	81 22 9 400 272, 83 22 0 402 413, ASW 3309, ETL 7045E, LA2634				
	83 22 0 136 376, 83 22 0 429 154, EZL 799 A, EZL 799, ZF CVT V1				
PORSCHE	000 043 304 00				
	000 043 205 28, 999 917 547 00				
	PDK, 000 043 20, 000 043 305 63, 000 043 207 29, 000 043 207 30, 999 917 080 00, 999 917 546 00, TF 0870				
VOLVO	31 256 774, 31 256 775				
	1161521, 1161540, 97340, 97342				
	1161520-7, 1161838, BOT 341				

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
CITROËN	05127382, 68043742AA, 68818925AA/AB, 8 & 9 Speed ATF, AW-1, AW-2, RP 9734 R7 for EAT6 transmissions				
	9730 AC, 9735-EJ, AL4 Automatic Gearbox Oil (# 9730.AE), JWS 3309, Z 000169756				
	1618078480, 9730 A8, 9734 S2, DCS, JWS 2271				
	9735 EF, Elfmatic CVT, Elfmatic CVT MV				
DS	05127382, 68043742AA, 68818925AA/AB, 8 & 9 Speed ATF, AW-1, AW-2, RP 9734 R7 for EAT6 transmissions				
	9730 AC, 9735-EJ, JWS 3309, Z 000169756				
	1618078480, 9730 A8, 9734 S2, DCS, JWS 2271				
	9735 EF, Elfmatic CVT, Elfmatic CVT MV				
FIAT	9.55550-AV5 for ZF automatic gearbox with 8 and 9speed				
	9.55550-AG1, 9.55550-AG2, 9.55550-AV1, 9.55550-AV2, 9.55550-AV4				
	9.55550-DA11, 9.55550-MZ2, 9.55550-MZ6, Tutela Transmission Gearforce				
	Tutela Car CVT N.G				
MASERATI	231603, M-1375.4				
	231603				
PEUGEOT	05127382, 68043742AA, 68818925AA/AB, 8 & 9 Speed ATF, AW-1, AW-2, RP 9734 R7 for EAT6 transmissions				
	9730 AC, 9735-EJ, JWS 3309, Z 000169756				
	1618078480, 9730 A8, 9734 S2, JWS 2271				
	9735 EF, Elfmatic CVT, Elfmatic CVT MV				
RENAULT	CLIP, DP0, Elfmatic J6, matic D2, matic D3				
	BOT 450, DC4, EDC				
	CVT CK/SK/FK, Elfmatic CVT, Elfmatic CVT MV				

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
ASTON MARTIN	4G4319A509 / AA / S				
JAGUAR	02JDE 26444, Jaguar Fluid 8432				
	Jaguar Fluid 8432				
	Jaguar Fluid 8432, JLM 20237, JLM 20238, M-1375.4				
	FFL-3				
LAND ROVER	02JDE 26444, Jaguar Fluid 8432 LR023288, LR023289, TYK500050				
	Jaguar Fluid 8432, TYK500050				
	Jaguar Fluid 8432, JLM 20237, JLM 20238, M-1375.4 M-1375.4, N402, STC 4863, TYK500050				
	FFL-3				
MG	EM-CVTF				
ROLLS-ROYCE	PL 31493PA				
ROVER	ATF 206				
	EM-CVTF, Unipart Transmatic ATF				
SAAB	93 165 147				
	93 160 393, 93 165 147, JWS 3309				
OPEL	GM 1940700, GM 1940767, GM 21005966 Transaxle, GM 2217466				
SEAT /SKODA	G 052 533, G 052 990				
	G 009 317, G 052 171, G 052 178, G 052 182, G 052 512, G 052 527, G 052 529, G 052 726, G 052 798, G 055 512, G 055 529, G 070 726, TL 52 182				
	G 052 180, G 052 516				
VAUXHALL	GM 1940700, GM 1940767, GM 21005966 Transaxle, GM 2217466				
	7-speed CVT, HP CVTF 95529854, VT40				

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
CHRYSLER	68157995AA, 68157995AB, 68218057CA, 68218058CA, 68218054CA, 68218925AA, 68171869AA, 68043742AB, 68157995AA, 68157995AB, 68171866AA, 68171869AA, 68218054CA, 68218057CA, 68218058CA, 68218925AA, ATF+3, ATF +4, DEXRON-VI Automatic Transmission Fluid, MS 90030-A5, MS 9602, Moper SP IV Automatic Transmission Fluid				
	ATF+3, ATF+4, MS 9602				
	ATF+, ATF+2, ATF+3, ATF+4, MS 5931, MS 7176, MS7176D, MS 7176E, MS 9602				
	CVTF+4, NS-2				
FORD	MERCON LV, MERCON ULV, WSS-M2C922-A1, WSS-M2C949-A, XT-10-QLVC, XT-6-QSP (SP)				
	ESP-M2C166-H, FNR5, M2C185-A, ESD-M2C186-A, MERCON, MERCON SP, MERCON V, SQ-M2C9010-A, WSA-M2C195-A, WSS-M2C138-CJ, WSS-M2C166-H, WSS-M2C924-A, XL-12, XT-2-QDX, XT-2-QDX (M), XT-2-QSM(Syn), XT-5-QM, XT-6-QSP, XT-8-QAW, XT-9-QMM5				
	1 490 761, 1 490 763, POWERSHIFT, WSS-M2C200-D2, WSS-M2C200-D3, WSS-M2C200-E1, WSS-M2C936-A				
	CVT23, CVT30, MERCON C, WSS-M2C928-A, WSS-M2C933-A, XT-7QCFT				
GENERAL MOTORS	9986153, 88861003, 88861004, 9986333, 19256039, 88863400, 88863401, 9986153, AW-1, Dex HP, 1940184, 93165414, DEXRON HP ATF, DEXRON II D, DEXRON III H, DEXRON ULV ATF, DEXRON VI, W16444, W16974, WS				
	DEXRON II D, DEXRON III H				
	19256039, 1940771, 1940773, 88861950, 88861951, 88900925, 9985010, DEXRON II D, DEXRON II E, DEXRON III G, DEXRON III H				
	1940713, 1940714, CVTF I-Green2, DEX-CVT, HP CVTF 95529854, VT40				
JEEP	ATF+3				
	05191184AA, CVTF+4, NS-2, VTF				

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
CHRYSLER	68157995AA, 68157995AB, 68218057CA, 68218058CA, 68218054CA, 68218925AA, 68171869AA, 68043742AB, 68157995AA, 68157995AB, 68171866AA, 68171869AA, 68218054CA, 68218057CA, 68218058CA, 68218925AA, ATF+3, ATF +4, DEXRON-VI Automatic Transmission Fluid, MS 90030-A5, MS 9602, Moper SP IV Automatic Transmission Fluid				
	ATF+3, ATF+4, MS 9602				
	ATF+, ATF+2, ATF+3, ATF+4, MS 5931, MS 7176, MS7176D, MS 7176E, MS 9602				
	CVTF+4, NS-2				
FORD	MERCON LV, MERCON ULV, WSS-M2C922-A1, WSS-M2C949-A, XT-10-QLVC, XT-6-QSP (SP)				
	ESP-M2C166-H, FNR5, M2C185-A, ESD-M2C186-A, MERCON, MERCON SP, MERCON V, SQ-M2C9010-A, WSA-M2C195-A, WSS-M2C138-CJ, WSS-M2C166-H, WSS-M2C924-A, XL-12, XT-2-QDX, XT-2-QDX (M), XT-2-QSM(Syn), XT-5-QM, XT-6-QSP, XT-8-QAW, XT-9-QMM5				
	1 490 761, 1 490 763, POWERSHIFT, WSS-M2C200-D2, WSS-M2C200-D3, WSS-M2C200-E1, WSS-M2C936-A				
	CVT23, CVT30, MERCON C, WSS-M2C928-A, WSS-M2C933-A, XT-7QCFT				
GENERAL MOTORS	9986153, 88861003, 88861004, 9986333, 19256039, 88863400, 88863401, 9986153, AW-1, Dex HP, 1940184, 93165414, DEXRON HP ATF, DEXRON II D, DEXRON III H, DEXRON ULV ATF, DEXRON VI, W16444, W16974, WS				
	DEXRON II D, DEXRON III H				
	19256039, 1940771, 1940773, 88861950, 88861951, 88900925, 9985010, DEXRON II D, DEXRON II E, DEXRON III G, DEXRON III H				
	1940713, 1940714, CVTF I-Green2, DEX-CVT, HP CVTF 95529854, VT40				
JEEP	ATF+3				
	05191184AA, CVTF+4, NS-2, VTF				



国内メーカー車両適合表

車両メーカー	メーカー品番, トランスミッション機種	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
DAIHATSU	AMMIX CVTF DFE, AMMIX CVT Fluid DC, AMMIX CVT Fluid DFE, CVTF 3320, CVT Fluid DFC, Fluid TC				
HONDA / ACURA	08200-9005, 08200-9008, 08200-9008A, 08200-9009A, 08200-9016-A, 08200-9017, 08266-9904, 08266-99907, 08266-99964, ATF-11, ATF-TYPE 3.1, B2618-OLE-025, Type 3.0				
	082000-9001, ATF DW-1 (except CVTs), ATF Z1 (except CVTs)				
	Special ATF Honda, Special Honda Power Steering Fluid				
	MTF-III				
	08200-9006, 08200-HCF-2, 0826099905HE, 087009006, HMMF (Honda Multi Matic Fluid) for CVT models only, without wet starting clutch, CVT-F, Genuine CVT Fluid, HCF-2, Z-1 (CVT models only, without starting clutch, not for Honda Jazz & Fit MY 2001-2007)				
ISUZU	Besco ATF III, SCS, WSI				
	ATF Z1 (except CVTs), Besco ATF II, H50235, SCS				
MAZDA	0000-77-122E-01, ATF FZ, MERCON LV				
	6-sp AT, ATF D-II, ATF F-1, ATF M-III, ATF M-V, JWS 3317				
	CVTF 3320, JWS 3320				
MITSUBISHI	4030401, ATF-MA1, ATF SPH-IV, ATF SP-IV, MZ320762, MZ320775				
	ATF-J3, Diamond / DiaQueen ATF SP II, SP III, ATF-PA				
	ATF-J2, AYC Fluid, Diamond / DiaQueen PSF, PSF 3				
	Diamond Queen SSTF-1				
	CVTF ECO J4, Dia Queen CVTF-J1, CVTF-J4, CVTF-J4+, MZ313973, SPIII (CVT models only)				
NISSAN / INFINITI	999MP-MPT10P, 999MP-MTS00P, KLE24-00002, MATIC P				
	MATIC D, MATIC J, MATIC K, MATIC W, MATIC S				
	ATF D3M, ATF FMS, PSF-II				
	DCT Fluid, GR6, LV MT-1				
	999MP-NS200P, KTF-1, N-CVT, NS-1, NS-2, NS-2V, NS-3				
SUBARU	ATF-WS				
	ATF HP, KO410Y0700, SOA868V9241				
	CV30, CVT III Fluid, CVT TR580, CVT TR690, ECVT, High Torque CVT, High Torque CVTF-LV, iCVTF, i-CVTF FG, K0421Y0700, K0425Y0710, K0425Y0711, Lineartronic chain CVT 3 Fluid, Lineartronic chain CVT and CVT II Fluid, Lineartronic CVTF, Lineartronic High Torque (HT) CVT Fluid, Lineartronic II, NS-2, SOA748V0300				
SUZUKI	MATIC S				
	JWS 2384K, JWS 3314, JWS 3317				
	99000-22B27-036				
	CVTF 3320, CVTF 4401, CVTF TC, CVT Green 1, CVT Green 1V, CVT Green 2, NS-2				
TOYOTA / LEXUS	00289-ATFWS, 08886-02303, 08886-02305, 08886-80803, ATF FZ				
	ATF Type T-IV, ATF WS, JWS 3324, NWS 9638				
	08886-00405, 08886-81015, ATF D-III, ATF Type T, ATF Type T-II, ATF Type T-III, JWS 2312D, JWS 3309, LF				
	08885-81001, JWS 2271, LF, LV 75W MT				
	CVTF 3320, CVT FE, Fluid FE, Fluid TC				



適合表(T/Mメーカー・他社)

トランスミッション メーカー	メーカー品番	ATF VI	Multi ATF	Multi DCTF	Multi CVTF
ALLISON TRANSMISSION	C-4				
	C-4, TES-295				
AISIN	ATF-0WS (except CVTs), AW-1, AW-2				
	AW-F21, CLIP, FF ATF, JWS 2312D, JWS 3309, JWS 3314, JWS 3317				
JATCO	1A				
	1A, JF613E				
ZF	##S671090255, ##S671090281, ##S671090312, AA01 500 001, Lifeguard 6, Lifeguard 6 Plus, Lifeguard 8, Lifeguard 9, M-1375.4, M-1375.5, M-1375.6, S671 090 255, S671 090 281, S671 090 312, TE-ML 11				
	Lifeguard 5, Lifeguard 6, S671 090 170, S671 090 255, TEMPL 03D, TE-ML 04D, TE-ML 09, TE-ML 09A, TE-ML 09B, TE-ML 14A, TE-ML 14B, TE-ML 16L, TE-ML 17C				
オイル メーカー	メーカー品番	ATF VI	ATF	DCTF	CVTF
APPOLLOIL	ATF Red-1K				
CASTROL	Transmax J, Transmax Z, TranSynd				
	BOT 118 Plus, BOT 341, BOT 342A, BOT 350 M1, BOT 350 M3, BOT 450, Transmax Dual				
ESSO	ATF LT 71141, JWS 3314				
	EZL 799, FN1975				
ELF	matic CVT, matic CVT MV				
IDEMITSU	ATF HP, K17				
	CVTF-EX1				
MOBIL	ATF 3309, ATF 3317				
	CVTF 3320				
FUCHS	ATF 3292, ATF 4400, ATF 6000 SL				
	TITAN 3353, TITAN ATF 4400				
JALOS	Class 1A-LV, M315				
MOPER	68218925AA				
	CVTF+4, CVTplus4				
PENTOSIN	FLL				
	FFL-2, FFL-3				
PETRONAS LUBRICANTS	Tutela Transmission AS8				
	Tutela GI-V, Tutela GI-VI, Tutela Transmission Force4				
	Tutela Transmission Gearforce				
	Tutela Car CVT N.G				
SHELL	#m, #13, L-12108, M-1375.4, M-1375.5, M-1375.6				
	3403(-M115), ATF 3353, LA2634, M-1375.4				
	TF 0870				
	Green 1V				
TEXACO	ETL 7045E, ETL 8072B, N402				
TOTAL	ATF H50235, Fluide AT 42				